



NOTE(S)

- 1) O-RING (ITEM 3) NOT SHOWN.
- 2) CONTACT SALES FOR REPLACEMENT PARTS.

3	O347BU	O-RING	NITRILE RUBBER	2
2	HU200400RN	4" FIG. 100/200/206 SPLIT HAMMER UNION REPAIR NUT	PAINTED STEEL	2
1	HUFMM2064T-1	4" 206 SERIES HAMMER UNION TEE	IRON	1
ITEM NO.	PART NUMBER	DESCRIPTION	MATERIAL	QTY



The Right Connection™

dixonvalve.com

PROPRIETARY AND CONFIDENTIAL

This drawing is owned by Dixon Valve & Coupling Co. and shall be returned upon demand. It is loaned on condition that it shall not be copied or reproduced or submitted to others without the owners consent. In accepting it subject to this condition the recipient further agrees that this drawing or any design detail or concept disclosed herein shall not be used in any way detrimental to or in competition with the owner. If the recipient does not agree to the terms of this agreement they shall return this drawing immediately. The information contained in this drawing is subject to change without notice.

DO NOT SCALE THIS DRAWING

DIXON U.S.A.

THE RIGHT CONNECTION™

TITLE: 4" 206 SERIES FEMALE x MALE x MALE HAMMER UNION TEE

MATERIAL: SEE BOM

PART NUMBER: **HUFMM2064T**